



## TECHNICAL DATA SHEET

# SUPERCEDE® X8

## Nitrile Exam Gloves

### PRODUCT DESCRIPTION

#### SPECIFICATIONS

PRODUCT:		Supercede X8	
GRADE:		Powder-Free Exam	
MATERIAL:		Nitrile	
THICKNESS	Finger:	7.2mil	0.18mm
	Palm:	6.2mil	0.16mm
	Cuff:	5.1mil	0.13mm
COLOR	Outer:	Light Blue	
	Inner:	Light Blue	
SURFACE	Outer:	Fully Textured	
	Inner:	Smooth	
LENGTH:		9.5"	242mm
WEIGHT*:		8.8g	
FIT TYPE:		Ambidextrous	
CUFF TYPE:		Beaded	
WATERTIGHT AQL:		0.65	
ORIGIN COUNTRY:		China	

#### PHYSICAL PROPERTIES

	PRE-AGING	POST-AGING
TENSILE STRENGTH:	21 MPa	20 MPa
ELONGATION:	580%	540%
FORCE AT BREAK:		

#### INTEGRATED TECHNOLOGIES

- **TouchTek®** Clean Glove Technology: Helps prevent contamination and skin irritation
- **MilTek®** offers durability and tactile sensitivity
- **SW Grip Technology** Fully textured surface for superior wet and oily grip



\*Specification based on size large gloves

### STANDARDS & CERTIFICATIONS

EN 420:2003	CAT III COMPLEX DESIGN
EN 374-3:2003	FDA 21 CFR 177.2600
EN 455:2000-2015	Component materials comply with FDA regulations for food contact.
ASTM D6319-10	Tested for use with Chemotherapy Drugs. Gloves used for protection against chemotherapy drug exposure should be selected specifically for the type of chemicals tested. For a complete list of the drugs and concentrations tested for, and testing method used, please call 510-429-8692.
ASTM F1671-97	
ASTM F739-12	
REACH EU 1907/2006	
DIRECTIVE 2011/65/EU	
EU Reg 528/2012	



Please visit [swsafety.com/symbols](http://swsafety.com/symbols) for information on standards used on this document.

### ORDERING

ITEM NO.	SIZE	PALM WIDTH	PACKAGING
N098312	S 6½ - 7	3.4" 85mm	50 gloves per box 10 boxes per case
N098313	M 7½ - 8	3.8" 96mm	50 gloves per box 10 boxes per case
N098314	L 8½ - 9	4.2" 106mm	50 gloves per box 10 boxes per case
N098315	XL 9½ - 10	4.5" 115mm	50 gloves per box 10 boxes per case
N098316	XXL 10½ - 11	4.9" 126mm	50 gloves per box 10 boxes per case

### APPLICATIONS

- Food Handling and Packaging
- Chemical Handling
- Janitorial Maintenance
- Painting

### STORAGE

Keep out of sunlight. Store in a cool, dry place. Keep away from sources of ozone or ignition.

